


# **Experian AutoCheck Report**

Report run: 05/01/2025 18:08:36 EDT

### 2013 Ford Fusion SE Sedan 4D (2.5L I4 SMPI Gasoline) VIN: 3FA6P0H77DR185599 Class: Car - Midsize Country of Assembly: Mexico Vehicle Age: 12 year(s) **Estimated In Service:** 11/25/2012 **Last Reported Odometer:** 183,178 (02/24/2025)





### **AutoCheck Score**

Similar vehicles usually range between 43 and 68

### Vehicle History at a Glance



**State Title Brand** 



**CLEAN** 



**Auction Brand / Issues** 

Structural Damage



**AUCTION ISSUE REPORTED** 



**Accident / Damage** 

Airbag Deployed,Structural Damage



**SEVERE** 



**Open Recall Check** 



2 OPEN RECALL(S)



**Insurance Loss / Transfer** 



**NO ISSUE** 



**Odometer Check** 

Last reported odometer: 183,178 (02/24/2025)



**NO ISSUE** 



**Certified Pre-Owned** 



**NO CPO INFO AVAILABLE** 



Service / Repair

1 Service Record(s) Reported



**NO ISSUE** 



**Additional History** 

Lien Reported, Corrected Title




**EVENTS REPORTED** 



### This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. Terms & Conditions

Learn More



Damage Date	Damage Type	Severity	
05/10/2017	Collision	Severe	
09/01/2017	Structural Damage	Severe	

Not all accidents and/or damage events are reported to Experian. Inspection by a third party prior to purchase is recommended. See **Detailed Vehicle History** for more information regarding accident/damage events.

## Open Recall Check



### Information Reported: AutoCheck found 2 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 06/09/2020

Recall Type - Safety

NHTSA / OEM Recall No. - 20V331 / 20S30

Campaign Description - Safety Recall: DOOR LATCH REPEAT REPAIR

Status: Remedy Available

Recall Date - 03/13/2023

Recall Type - Safety

NHTSA / OEM Recall No. - 23V162 / 23S12

Campaign Description - Safety Recall: FRONT BRAKE FLEXIBLE HOSE REPLACEMENT

Status: Remedy Not Available

More information including remedy or risk factors. Locate your nearest authorized Ford Dealer to schedule repair.

### Odometer Check



### **Your Vehicle Checks Out**

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



### **State Title Odometer Check**

No issues reported



### **Auction Odometer Check**

No issues reported



### **Odometer Calculation Check**

No issues reported



### Detailed Vehicle History

2012

# **Vehicle Prep and Other Pre-Titling Events**

Preparation	Date: 11/2012			
Event Date	Location	Odometer	Data Source	Details
11/25/2012			Independent Source	Vehicle Manufactured and Shipped to Dealer
12/27/2012	CA		Dealer Record	Vehicle in Dealer Inventory
12/27/2012	CA	5	Motor Vehicle Dept.	Odometer Reading from DMV
01/09/2013	ОН	5	Dealer Record	Vehicle in Dealer Inventory

2013

# Owner 1

Location: VA	Owned From	: 01/2013	Usage: Fleet, Lease	
Event Date	Location	Odometer	Data Source	Details
01/15/2013	CA		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
01/24/2013	CA		Motor Vehicle Dept.	Title(Leased Vehicle)
12/05/2013			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 13N03 Warranty Extension - Single Repair: ELECTRONIC THROTTLE BODY EXTENDED COVERAGE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
08/20/2014			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 14N02 Warranty Extension - Single Repair: EXTENDED WARRANTY COVERAGE FOR PCM REPROGRAMING IN THE EVENT OF ABS VEHICLE SPEED SIGNAL RELATED COM LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
05/10/2017	CA		Police Report	Accident Reported(Report #:9655-2017-13516) Multiple Impact Collision Air Bag Deployed Vehicle Was Towed
06/01/2017	CA		State Agency	Accident Reported, Event Date is Date Reported to AutoCheck
06/24/2017	PACIFIC SW REGION	96,871	Auto Auction	Reported at Auto Auction
06/26/2017	CA	96,871	Auto Auction	Auction Announced as Fleet/Lease(COLOR REPORTED AS WHITE)
08/28/2017	CA	96,876	Auto Auction	Reported at Auto Auction as Dealer Vehicle
08/30/2017	PACIFIC SW REGION	96,876	Auto Auction	Reported at Auto Auction
09/01/2017	PACIFIC SW REGION		Auto Auction	Auction Announced as Structural Damage



# 2018

# Owner 2

Location: UT	Owned From: 0	01/2018	<b>Usage</b> : Personal	
Event Date	Location	Odometer	Data Source	Details
01/02/2018	OREM, UT		Motor Vehicle Dept.	Title(Lien Reported)
01/03/2018	OREM, UT		Motor Vehicle Dept.	Registration Event/Renewal
01/25/2018	OREM, UT		Motor Vehicle Dept.	Title(Lien Reported)
03/28/2018	SANDY, UT	103,961	Dealer Service	Multiple Point Vehicle Inspection Recommended Maintenance Performed
01/03/2020	OREM, UT		Motor Vehicle Dept.	Registration Event/Renewal
11/04/2020	OREM, UT		Motor Vehicle Dept.	Title(Lien Reported) Corrected Title(Lien Reported)

Location: ID	Owned From: 1	1/2020	Usage: Personal	
Event Date	Location	Odometer	Data Source	Details
11/10/2020	BLACKFOOT, ID		Motor Vehicle Dept.	Registration Event/Renewal
11/15/2020	BLACKFOOT, ID		Motor Vehicle Dept.	Title
08/16/2021	BLACKFOOT, ID		Motor Vehicle Dept.	Registration Event/Renewal
07/07/2023	BLACKFOOT, ID		Motor Vehicle Dept.	Title
07/12/2023	BLACKFOOT, ID		Motor Vehicle Dept.	Registration Event/Renewal
02/03/2025	BLACKFOOT, ID	183,107	Dealer Listing	Vehicle Listed for Sale
02/24/2025	МО	183,178	Auto Auction	Reported at Auto Auction

#### **AutoCheck Terms and Conditions**

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

#### **Buyback Protection Terms and Conditions**

This vehicle (3FA6P0H77DR185599) qualifies for **AutoCheck Buyback Protection**. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

#### **About AutoCheck**

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

#### **Patent Notice**

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.